

	ANA COUNTRY OF THE STATE OF THE		William Charles and Charles an	S DIE CON CONTROL POLICE DES CONTROL POLICE DE LA CONTROL		H THE LOSS PROPERTY.
TYPE OF INSPECTION: CAFO COMPLAINT (NEORMALION ECTION: COMPLAINT RECONNAISSANCE			OPERATOR REQUEST	Потнек	
FACILITY NAME (LL	Corp	e proprietorship, etc.)		INSPECTION DATE	ARRIVAL TIME	L TIME
ADDRESS 19753 E. 2200 St.		:	INSPECTOR(s) E. Ackerman & S. Fow	s) 1 & S. Fowler	DEPARTURE TIME ~3:00 PM	RE TIME
CITY Atkinson	STATE	ZIP CODE 61235	ACCOMPANIE None	ACCOMPANIED BY (if applicable) None	ble)	
LEGAL DESCRIPTION	COUNTY	SECTION TOWNSHIP R	RANGE TEMPER	VATURE	PRECIPITATION TYPE Sunny to Cloudy	ON TYPE
Facility Owner(s):	NAME Ralph Diericks	CON NO.	CONTACTED PH	PHONE Exemption 6 and	MOBILE and Exemption 7(C)	n 7(C)
	ADDRESS (Comption 6 and Exemption 6	cry xemption 7(C)		STATE	ZIP CODE	
	NAME	CONTACTED ☐ YES ☐	N O	PHONE	MOBILE	
	ADDRESS	CIIY	The state of the s	STATE	ZIP CODE	
Eacility Operator(s): NAME	NAME	CONTA	CONTACTED PH	PHONE	MOBILE	
	ADDRESS	CITY		STATE	ZIP CODE	
	NAME	CONT/	□ NO	PHONE	MOBILE	
	ADDRESS	CITY	And the state of t	STATE	ZIP CODE	
NPDES PERMIT	NPDES PERMIT INFORMATION (If no NPDES Permit, skip this section)	PDES Permit-skip th	is section)			
 What type of N	What type of NPDES permit has been issued? Individual NPDES Permit	General NPDES Permit	mit		NPDES	#
What date wasWhat date doe	What date was the NPDES permit expire?	7				
	Is a copy of the NPDES permit onsite?	Total tradematerial and the second se			☐ YES	□ 8
	Permitted number of animal units?]	
Does the NPDEHave there been	Does the NPDES Permit contain a compliance schedule? Have there been any changes made to the production area since the permit was issued?	ance schedule? e production area since	the permit w	/as issued?	YES	
If "YES", provi	If "YES", provide a detailed description of those changes	those changes.				
Yone						

Facility Name: Exemptions 6 and 7(C)
Diericks Swine Farm Inspection Date: May 5, 2011 Page 2/7

LAND APPLICATION INUTRIENT MANAGEMENT		
How many TOTAL acres are available for land application? 400		
2. How many acres are KEADILY available for land application at the time of inspection?		acres
tons		
5. Does the facility have a contractor perform land application? If "YES", Name of Contractor: Justin Peterson (Out of Landmark)	⊠ YES	O N
ication equipment is available to the facility?		
☐ Umbilical Injection ☐ Honeywagon Injection ☐ Honeywagon Surface ☐ Irrigation	tion	
\square Rotational Gun \square Manure Spreader \square Vegetative Filter \boxtimes Other $\underline{\hspace{0.5cm}}$ Inject	Inject with Tanks	S
7. Does the facility calibrate the land application equipment? If "YES", What method is used?	X YES	N
Contracted 8. Does the facility land apply within the 150 foot setback from any water well?	⊠ YES	□ 8
If "YES", Explain Contracted		
and apply within the 200 foot setback from any surface water?	⊠ YES	O N
	1	
10. Does the facility land apply near any residences? If "YES", Explain Exemptions 6 and 7(C) one neighbor within 1/4 mile Contracted		□ NO
11. Is livestock waste transferred off-site to another party? If "YES", Are records of manure transfers kept? If "YES", Ask to see records	☐ YES	NO O
12.Does the facility have a current NMP or CNMP? If "YES", Does the facility maintain a copy of the nutrient management plan (NMP) onsite?	⊠ YES □ YES	□□ N O
13. Does the NMP reflect the current operational characteristics (number of animals, cropping, etc.)?	⊠ YES	NO O
14. Are the number of acres owned/leased consistent with those in the NMP?		□ NO
15.Is manure and wastewater being applied in accordance with setback/buffer requirements of the NMP?	⊠ YES	ON
16. Are all of the records identified in the NMP being maintained and kept current?	⊠ YES	□ NO
17. Are records being maintained at the required frequency?	⊠ YES	ON
18. Are records being maintained onsite for the period required by NMP and/or NPDES permit?	☐ YES	ON
19. Is the NMP adequately addressing the storage, handling and application of manure and wastewater to prevent discharges to waters of the U.S.?	☐ YES	□ No

Exemptions 6 and 7(C) Inspection Date: May 5, 2011 Page 3/7

LIVESTOCK ACTORNOCESCRIPTION Facility Type	Tion.			
Total Confinement Buildings Open Confinement Buildings	□ op	Open Earthen Feedlot Vegetated Pasture		
Open Concrete Feedlot	0t	Other		
Type of Animals	Number of Animals (currently)	Capacity	Type of Confinement	
SWINE > 55 LBS	0	3300	Total	
Does the facility have an Illinois Certified Livestock Manager (300 or greater animal units)?	led Livestock Manager (300 or o	preater animal units)?	N/A X YES T	2
If greater than 1000 animal units but less than 5000 animal units, does the facility have a waste management plan?	t less than 5000 animal units,	does the facility have	□ N/A	2
If greater than 5000 animal units, has the facility submitted a waste management plan to DOA for review?	as the facility submitted a was	te management plan	to N/A Tes T	3
Does the facility have any other locations under common ownership, or where equipment and/or manure is shared, or where the other site shares land application sites? If so, put names and addresses below. None	tions under common ownersher site shares land application :	ip, or where equipme sites? If so, put namo	es and	N
		·		
LIVESTOCK WASTE STORAGE Does the facility have any existing livestock waste containment system? If NO, then proceed to question 10.	ing livestock waste containme 10.	nt system? 🛛 YES	□ NO	
General description of the waste containment system (include solid and liquid manure handling, mortality, and feed storage areas).	e containment system (include	solid and liquid man	ure handling, mortality, a	nd
Manure is stored in a above ground slurry tank, which at the time of the inspection appeared to be bending out at the bottom.	ground slurry tank, which	at the time of the i	inspection appeared t	o be
Mortalities are rendered using Schnowske rendering service. The mortalities a box on the north end of the slurry tank until hauled away. The pick-up is once	ng Schnowske rendering s slurry tank until hauled av	ervice. The mortali vay. The pick-up is	ities are stored in a 8'X8' once a week.	X 8'

'n MORTAL INES MANAGEMENT 9 10. œ Ò 'n 4. ω Type of Storage Are mortalities documented and are records kept? How are mortalities managed? None Other None discharge). None Rendering- Schnowske If "YES", provide a detailed description of the area(s) of concern: Are there any portions of the production area where runoff is not controlled? If "YES", please provide a description (overflow pipe, spill way, etc. Include a description the area receiving the Does the system have an outfall or discharge point? Are the routine visual inspections documented? \boxtimes YES Do facility personnel perform routine visual inspections of the storage structures? Vegetative Filter Manure Stacks Above Ground Storage Tank ("Slurrystore") Estimated final stage storage structure freeboard Do the storage structures have adequate freeboard? Are levels of manure in the storage structures recorded and records kept? Do the storage structures have depth markers or staff gauges? Anaerobic Digester **Underfloor Pits** Impervious Soil Pad Concrete Pad Roofed Storage Shed Settling Basin Holding Pond Below Ground Storage Tank Covered Lagoon Anaerobic Lagoon **Diericks Swine Farm** (Composted, buried, burned, rendering service, other) 1.5 Million Gallons-emptied every fall Total Storage Capacity (Specify Units) ~66 \boxtimes ΥES YES YES 중 8 Inspection Date: May 5, 2011 ŒS 8 8 \boxtimes YES S ΥES 贸 S Z O S

Facility Name:

Exemptions 6 and 7(C)

Page 4/7

	JRCES
 What type of metho 	What type of method is used to provide drinking water for the animals?
Overflow waters	s 🗌 Tip Tanks 🛚 Nipple waters 🔲 Water Bowls 🔲 Other
 How is the water for animals obtained? ☐ Community PWS ☒ On-Site We deep 	r animals obtained? S 🔯 On-Site Well 🔲 On-Site Impoundment 🔲 Other New well 415 '
3. Is a mist cooling system used? How is mist water contained?	stem used? 🛛 YES 📋 NO
Water falls into pi	Water falls into pit works in 15 min. cycles from 10AM - 8PM
DAIRY OPERATION (II	DAIRY OPERATION (If No Dairy, supplints section)
 How many times per 	How many times per day are cows milked?
2. Describe how the da	how the dairy's non-contact cooling water is contained (Example: it is reused for drinking water for
None	
 Describe how the minimizer is contained. None 	Describe how the milking parlor is cleaned (hose or flush) and where the process wastewater goes and how it is contained. None
4. Describe how the tar None	Describe how the tank(s) are washed and where the process wastewater goes and how it is contained. None
5. Describe where proc None	Describe where process wastewater from the plate cooler goes and how it is contained. None
BEDDING (# No Beddi	(If No Bedding, skip this section)
Describe what type one None	Describe what type of bedding is used for the animals. None
2. Describe how beddin None	Describe how bedding is collected and how often. None
What is done with the used bedding?	ne used bedding? Reused Land Applied

Facility Name

Exemptions 6 and 7(C)

Inspection Date:

Page 6/7

Cc: BOW/DWPC/RU 'n None Facility Name: Diericks Swine Farn Exemptions 6 and 7(C) INSPECTORSSIGNATURE Will an inspection report be attached? \boxtimes The slurry tank needs to be inspected by Cady, to see if the bending occuring at the bottom of the tank is structurally sound. This slurry tank has had sheets replaced in it. OTHER COMMENTS/ NO TES DISCHARGES Ġ Ō ָם Is the facility currently discharging livestock waste from the production area? If "NO" proceed to next section. _ ന Φ $\overline{\mathbf{C}}$ Ö ö Have there been any documented discharges of livestock waste to surface water past year? If "NO" proceed to question 2. What is the reason for the discharge? What was the precipitation amount? (if applicable, Was the discharge the result of a 25 year-24 hour rainfall event? If "YES", specify the date(s). Has the facility taken corrective action to remedy the situation which caused the Was IEMA notified of the discharge? If "YES", describe actions taken: discharge(s)? What was the precipitation amount? (if applicable) Was the discharge the result of a 25 year-24 hour rainfall event? What was the reason for the discharge? ŒS 8 REPORTSOATE Inspection Date: Attachments: in the Mav 5, 2011 YES ΥES YES YES YES ΥES Report/Fig. Page 7/7 □ No 8 8 N_O 8 g

1-2/Photographs

IEPA -**BOW** - Peoria

Exemptions 6 and 7(C)

Inspection Report

Subject: Henry County

(Atkinson)

Atkinson, IL 61235 19753 E 2200 St. Diericks Swine Farm

To: DWPC/FOS & RU

From: Star M. Fowler DWPC-FOS, Peoria Region

May 5, 2011

Date:

cloudy and the temperature was approximately 53°F. Bio-security measures were observed. The Checklist. following paragraphs provide further details of the field visit that compliment the CAFO photographs of the area are attached to this report. Weather conditions for the day were sunny to contacted after the inspection occurred. A plan view and various drawings of the site and digital inspect the wean to finish facility. Ralph Diericks is the owner of the facility and he was On May 5, 2011 at 10:00 AM Eric Ackerman and I visited Diericks Swine Farm S

Location:

description of this facility is the 1/4 NE, Section 34, (Loraine Township) in Henry County. The site is located in the watershed of the Green River. This facility is located approximately 6 miles north of Atkinson at road 2450N. The legal

Site Description:

Mr. Diericks purchased this site 7 years ago in January 2012, previously it was called Harms, Donald Swine Farm. This site is a wean to finish operation. The hogs are finished for Murphy-

Mr. Diericks has just added a new 415' deep well on-site for the facility

Total Confinement Buildings:

system is a manual system that is turned on each morning. From the collection tank the manure under them. A scraper system is used to gravity feed into the collection tank. This scraper 1,100 head hogs, for a total capacity of the site of 3,300 hogs. The buildings have 13" deep pits is then pumped into slurry tank. This facility has 3 total confinement buildings on site. They all hold a maximum capacity of

Manure Management:

to apply to. There is also one neighbor who owns 80 Acres of land that uses some of the manure manure is injected beneath the surface using tank wagons. Mr. Diericks owns 400 acres of land land application of the manure is contracted out to Justin Peterson, out of Landmark. The The slurry tank on-site is a 1.5 Million Gallon tank. This tank is emptied once a year during the An estimated yearly amount of 1.2 Million Gallons of manure is generated per year.

Slurry Tank:

if someone can come out and inspect the tank to make sure it is structurally sound. were many markings on the outside of the tank where paint was flaking off the tank (See thought the slurry tank has looked that way since he first purchased the property. There also Photograph #4.) We suggested to Mr. Diericks to call CADY INC. about the slurry tank and see inspection appeared to be bending outward (See Photograph #3.) Mr. Diericks stated that he This slurry tank has had some sheets replaced in it a few years ago. The slurry tank during the

release valve. See Photographs #1 & 5. A stream located to the direct south of the slurry tank manure release. enters into the Green River. The stream at this time appeared to be un-affected from the small There seemed to be evidence around the slurry tank of a recent minor release of manure from the

monthly reports are sent in. each ring ~44" tall the freeboard is ~66". The slurry tank freeboard is measured regularly and At the time of the inspection the slurry tank had approximately 1 and ½ rings of freeboard, with

Nutrient Management Plan:

of Toulon created the NMP. The NMP is up-dated every spring by Mowers. The facility has a Nutrient Management Plan (NMP) for the site. Mowers Soil Testing Plus out

Mortalities:

8'X8' storage box located on the north side of the slurry tank. comes once a week to pick up all mortalities. Until they are picked-up mortalities are held in an All the mortalities on this site are rendered using Schnowske Rendering Services. Schnowske

Conclusion:

representative from CADY INC. needs to come to the site and report on the findings in regards the release valve on the tank needs to be inspected to make sure it is functioning properly. A to issues with the slurry tank at this time In conclusion for this inspection the slurry tank needs to be inspected for structural integrity and

- 1) Bottom ring bending outward.
- 2) Paint chipping off the sides.
- 3) Release Valve integrity.

This report is submitted for your information.

-CAFO Checklist

Star M. Fowler

Att:

-Figures 1-2

-Photographs

cc: -Bruce Yurdin, BOW

-Peoria Files




Figure 1. Location Map of Diericks Swine Farm Atkinson in Henry County on May 5, 2011. Exemptions 6 and 7(C)





Figure 2. Plan View From Google Earth of Diericks Swine Farm on May 5, 2011.

Diericks Swine Farm
Henry County
May 5, 2011

(IEPA Star M. Fowler)



Photograph #1. Slurry Storage Tank small manure release below valve. View is west.




Photograph #2. Collection Tank that pumps to Slurry Tank. View is northeast.



May 5, 2011





Photograph #4. Markings on Slurry Tank, where there appears to be damage.

Diericks Swine Farm
Henry County
May 5, 2011

